



Models	UT30H	UT308H
Page	100	100
		
Measurement range (object)	0°C~100°C	0°C~100°C
Accuracy (object)	±1.0°C	±1.0°C
Measurement range (body)	32.0°C-45.0°C	32.0°C-45.0°C
Accuracy (body)	±0.3°C	±0.2°C
Resolution	0.1°C	0.1°C
Data storage		32 groups
Optimum measuring distance	1~5cm	1~5cm
Unit conversion (°C/°F)	●	●
Measurement alarm (body only)	Sound alarm for >37.2	Sound alarm for >37.2
Power on self test	●	●
Auto power off	●	●
Backlight	●	●
Operating environment	15°C-35°C, <85%RH	15°C-35°C, <85%RH
Transport and storage environment	-20°C-60°C, <93%RH	-20°C-60°C, <93%RH
Operating atmosphere pressure	700hPa-1060hPa	700hPa-1060hPa
Power	1.5V AAA x 2	1.5V AA x 2
Certificates	CE0413/FDA/UKCA	CE0413/FDA/UKCA